

Some photos taken during Rufuha wetland restoration activities in Rweikiniro Sub-county Ntungamo district. Activity was done in September and October 2019.



The 1st photo shows Tumwebaze Dinah - the District Environment Officer presenting and the 2nd photo shows the district Chairperson presenting his remarks at the district level stakeholders meeting



The 1st photo shows the environment officer Tumwebaze Dinah presenting at village level and the 2nd photo is at sub-county level meeting.



The above photo shows the MWE, District and Sub-county team officiating off the restoration activity headed by Businge Daniel RWC-W. all the eucalyptus in the bach ground was removed from the wetland and drainage channels covered.



The above photo shows the MWE, District and Sub-county team officiating at the 2nd day of Rufuha wetland restoration. Here they were blocking drainage channels.



The above photo shows the restored wetland section after removal of eucalyptus tree species and blocking the drainage channels by the community members.



The above photo shows a section of the wetland planted with eucalyptus exotic tree species before it was removed from the wetland.



The above photo shows a restored wetland section after removal of eucalyptus tree species from the wetland and blocked channels.




The above photo shows the Businge Daniel -RWC-W showing the RDC Ntungamo-Bakunda George (in suit) and DISO - Tandeka Apollo the extent of restoration of activity of Rufuha wetland.



The above photo shows journalists interviewing the RDC – Ntungamo (Bakunda George) on the wetland restoration activities



The photos shows community members opening drainage channels which blocked water from flowing all over the wetland.



The 1st photo shows communities opening the drainage channel and the 2nd photo shows after the channel had been opened to allow water flow all over Rufuha wetland.



The 1st photo shows restoration activities by blocking drainage channels to allow water spread in the wetland in progress and in the 2nd photo are some of the wetland restoration committee members overseeing the communities restoring.



Businge Daniel – RWC-Western being interviewed by the news reporters during Rufuha wetland restoration activities. As communities in the ground do the restoration.

Businge Daniel

REGIONAL WETLANDS COORDINATOR-WESTERN